

Fig.1





Fig.2






Fig. 3




Fig.4




Fig. 5




Fig. 6




Fig. 7





Fig. 8

9/18

Fig.9

(a) PARTY ENLARGED
VIEW



(b) PARTY ENLARGED
VIEW




Fig.10




Fig.11





Fig.12UNIT OF NUMBERS : μm





Fig. 13UNIT OF NUMBERS : μm

Fig. 14

(b)



(a)



(c) DIRECTION OF COORDINATE AXES

UNIT OF NUMBERS : μm


Fig.15UNIT OF NUMBERS : μm


Fig.16UNIT OF NUMBERS : μm



Fig.17UNIT OF NUMBERS : μm

Fig. 18UNIT OF NUMBERS : μm